


HP.BCS

HP.BS

HP.CS

HP.SBS



— IWATA ECLIPSE SERIES AIR BRUSHES • MASTER PARTS LIST —

#	ITEM DESCRIPTION	ITEM #	HP-BCS
1	Needle Cap	I6011	y
2	Nozzle Cap	E5 I6021	y
		E3 I6022	OPT
3	Cap	I6031	y
4	Nozzle	E5 I6041	y
		E3 I6042	OPT
5	O-ring	I6051	y
6A	HP-BSC Body *	-	y
6B	HP-BS Body *	-	x
6C	HP-CS Body *	-	x
6D	HP-SBS Body *	-	x
7	Air Valve O-ring	I5801	y
8	Air Valve Guide Body	I6081	y
9	Air Valve	I6091	y
10	Air Valve Spring	I5104	x
11	Air Valve Guide Screw	I6111	y
12	Main Lever	I6121	y
13	Needle Packing Screw Set (PTFE)	I7251	y

#	ITEM DESCRIPTION	ITEM #	HP-BCS	HP-BS	HP-CS	HP-SBS
16	Spring Guide	I7701	y	y	y	y
17	Needle	E5 I6171	y	OPT	OPT	OPT
		E3 I6172	OPT	y	y	y
18	Needle Chucking Nut	I1202	y	y	y	y
19	Single Cut Handle	I6191	y	y	y	y
	Preset Handle	I1552	OPT	OPT	OPT	OPT
	Bottle 2 oz / 60 ml	A4702	y	x	x	x
21	Lid	I6181	x	x	y	x
22	Cup (Side) 0.05 oz / 1.50 ml	I0703	x	x	x	y
	Cup (Side) with Lid 0.24 / 7 ml	I0704	x	x	x	OPT
22A	Cup Lower Lid	0.05 oz / 1.50 ml I0956	x	x	x	y
		0.24 / 7 ml I0957	x	x	x	OPT
22B	Cup Packing Lower Lid	I1505	x	x	x	y
23	Blanking Cover	I0452	x	x	x	y

14	Needle Chucking Guide	I7151	y	y	y	y
15	Needle Spring	I1352	y	x	x	x
		I1351	X	y	y	y

y = yes

X = no

OPT = Optional