


SPARMAX SP-575 Airbrush Parts List



INDEX	DESCRIPTION	INDEX	DESCRIPTION	INDEX	DESCRIPTION
1	Needle Cap	19	Piston O-ring	27	Handle
2	Nozzle Cap	20	Air Valve O-ring	28	Bottle Cap
3	Nozzle	21	Air Valve Set	29	Connector Bottle Cap
4	Body	21-1	Air Valve Set	30	22cc Glass Bottle
6	Push Button	21-2	Air Valve Set	31	80cc Plastic 80ftle
8	Needle Packing O-ring	22	Hose Connector Nut	32	Adjusting Screw
9	Needle Packing Screw	23	Hose Connector	33	Nozzle Plate O-ring
11	Needle Chucking Guide	24	Wrench	34	Nozzle Plate
12	Spring	25	Needle	35	Metal Assembly Tube
13	Spring Case	26	Needle Chucking Nut		